

SUSPECT ADVERSE REACTION REPORT

I. REACTION INFORMATION

1. PATIENT INITIALS (first, last) PRIVACY	1a. COUNTRY GUATEMALA	2. DATE OF BIRTH			2a. AGE 11 Years	3. SEX Female	3a. WEIGHT Unk	4-6 REACTION ONSET			8-12 CHECK ALL APPROPRIATE TO ADVERSE REACTION <input type="checkbox"/> PATIENT DIED <input type="checkbox"/> INVOLVED OR PROLONGED INPATIENT HOSPITALISATION <input type="checkbox"/> INVOLVED PERSISTENT OR SIGNIFICANT DISABILITY OR INCAPACITY <input type="checkbox"/> LIFE THREATENING
		Day	Month	Year				Day	Month	Year	
		PRIVACY						Unk			

7 + 13 DESCRIBE REACTION(S) (including relevant tests/lab data)
 Event Verbatim [LOWER LEVEL TERM] (Related symptoms if any separated by commas)
 were not instructed on the correct orientation of the ampoule [Health care provider instructions for product use lacking]
 they were not instructed on the correct orientation of the ampoule (which should be facing upward)/the cartridge needed to be oriented upward to prevent leaks [Device use error]
 significant amount of the product leaked out when she inserted the ampoule into the pen [Device leakage]

 Case Description: This is a spontaneous report received from a Consumer or other non HCP from product quality group, Program ID: 164974.

 (Continued on Additional Information Page)

II. SUSPECT DRUG(S) INFORMATION

14. SUSPECT DRUG(S) (include generic name) #1) Genotropin Pen (SOMATROPIN) Solution for injection #2) Genotropin Pen (SOMATROPIN (DEVICE CONSTITUENT)) Solution for injection		20. DID REACTION ABATE AFTER STOPPING DRUG? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
15. DAILY DOSE(S) #1) 0.8 mg, daily #2)	16. ROUTE(S) OF ADMINISTRATION #1) Unknown #2) Unknown	
17. INDICATION(S) FOR USE #1) Unknown #2) Unknown		21. DID REACTION REAPPEAR AFTER REINTRODUCTION? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> NA
18. THERAPY DATES(from/to) #1) Unknown #2) Unknown	19. THERAPY DURATION #1) Unknown #2) Unknown	

III. CONCOMITANT DRUG(S) AND HISTORY

22. CONCOMITANT DRUG(S) AND DATES OF ADMINISTRATION (exclude those used to treat reaction)		
23. OTHER RELEVANT HISTORY. (e.g. diagnostics, allergies, pregnancy with last month of period, etc.) From/To Dates Type of History / Notes Description Unknown		

IV. MANUFACTURER INFORMATION

24a. NAME AND ADDRESS OF MANUFACTURER Pfizer S.A. Laura Arce Mora Avenida Escazú, Torre Lexus, piso 7. Escazú San jose, COSTA RICA		26. REMARKS	
	24b. MFR CONTROL NO. PV202500063204		25b. NAME AND ADDRESS OF REPORTER NAME AND ADDRESS WITHHELD.
24c. DATE RECEIVED BY MANUFACTURER 04-JUL-2025	24d. REPORT SOURCE <input type="checkbox"/> STUDY <input type="checkbox"/> LITERATURE <input type="checkbox"/> HEALTH PROFESSIONAL <input checked="" type="checkbox"/> OTHER: Spontaneous		
DATE OF THIS REPORT 07-JUL-2025	25a. REPORT TYPE <input type="checkbox"/> INITIAL <input checked="" type="checkbox"/> FOLLOWUP: 2		

ADDITIONAL INFORMATION**7+13. DESCRIBE REACTION(S) continued**

An 11-year-old female patient received somatropin (GENOTROPIN PEN), (Batch/Lot number: unknown) at 0.8 mg daily. The patient's relevant medical history and concomitant medications were not reported.

The following information was reported: PRODUCT COMMUNICATION ISSUE (non-serious), described as "were not instructed on the correct orientation of the ampoule"; DEVICE USE ERROR (non-serious), described as "they were not instructed on the correct orientation of the ampoule (which should be facing upward)/the cartridge needed to be oriented upward to prevent leaks"; DEVICE LEAKAGE (non-serious), described as "significant amount of the product leaked out when she inserted the ampoule into the pen". The action taken for somatropin was unknown.

Causality for "were not instructed on the correct orientation of the ampoule", "they were not instructed on the correct orientation of the ampoule (which should be facing upward)/the cartridge needed to be oriented upward to prevent leaks" and "significant amount of the product leaked out when she inserted the ampoule into the pen" was determined associated to device constituent of somatropin (malfunction).

Product Quality Group provided investigational results on 03Jun2025 for somatropin (device constituent): Site Investigation (Pfizer manufacturing site): No further investigation was required as no valid lot number or returned sample was available. This complaint will continue to be trended. If additional information becomes available, this complaint will be reopened. Device Investigation: This investigation is based on the information captured in the Complaint Description and Argus Report. The Complaint Issue of "Leaking During Loading" was reported. The Risk Management File was reviewed to confirm that the Hazard(s) and Hazardous Situation(s) associated with the Complaint Issue are documented in the Hazard Analysis (INX100281795), Version (9.0). All complaint investigations are trended. There is not a current trend alert documented.

Additional Information: The patient's mother stated that a couple of months ago, she had already sent an email with some videos, as she had filed a complaint because a significant amount of the product leaked out when she inserted the ampoule into the pen. She was requesting a replacement for the medication that was lost during the insertion process. Additionally, she mentioned that after the initial training with a nurse on how to use the product, she received a request for information via email, which she completed by submitting a form along with the required evidence. However, during the first two training sessions, they were not instructed on the correct orientation of the ampoule (which should be facing upward). She had recordings of these training sessions, which she had sent by email, showing that this essential step was omitted. As a result, when she installed the cartridge following the initial instructions, the product was lost. It wasn't until a third training session, conducted by a different nurse, that the issue was identified and corrected. They were then informed that the cartridge needed to be oriented upward to prevent leaks. Due to this deficiency in the initial training, two ampoules were wasted. The patient's mother did not want to provide further information because she had already submitted all the necessary data and wanted follow-up on what she had already sent. She insisted that someone from PRIVACY should take responsibility for the lost ampoule. She also mentioned that the form had been submitted back in October of the previous year.

Follow-up (03Jun2025): This is a follow-up report from product quality group providing investigation results.

Follow-up (04Jul2025): Follow-up attempts are completed. Batch/lot number is not provided, and it cannot be obtained.